

Summary Report of Hazardous Waste and Sewage Spill Incidents per Water Code Section 13271

I. Petroleum Products

Date Reported*	Date Discovered	Discharger	Location	Problem	Action
5/4/04	4/30/03	WEIR CANYON HONDA	8323 LA PALMA, EAST, ANAHEIM	UNDERGROUND STORAGE TANK LEAK: CONTAMINATED SOIL	LEAK BEING CONFIRMED
5/17/04	5/11/04	EUCLID SHELL	2431 EUCLID AVENUE, ONTARIO	UNDERGROUND STORAGE TANK LEAK: CONTAMINATED SOIL	NO ACTION
5/17/04	5/17/04	SPARTAN CLEANUP CORP.	1890 MARKET STREET, RIVERSIDE	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	LEAK BEING CONFIRMED
5/19/04	4/9/04	FORD OF GARDEN GROVE	9222 TRASK AVE, GARDEN GROVE	UNDERGROUND STORAGE TANK LEAK: UNLEAD GASOLINE CONTAMINATED SOIL	LEAK BEING CONFIRMED
5/22/04	5/22/04	EQUITY OFFICE PROPERTY	2600 MICHELSON DR., IRVINE	UNDERGROUND STORAGE TANK LEAK: DIESEL CONTAMINATED SOIL	SITE WORKPLAN SUBMITTED
5/27/04	5/20/04	CIRCLE K #5802	16900 FOOTHILL BOULEVARD, FONTANA	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	POLLUTION CHARACTERIZATION
6/7/04	6/7/04	MOBIL #18-D7Y	6608 INDIANA AVENUE, RIVERSIDE	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	LEAK BEING CONFIRMED
6/7/04	6/7/04	CDF STATION #1	210 W. SAN JACINTO AVENUE, PERRIS	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	LEAK BEING CONFIRMED
6/9/04	5/20/04	SBC SERVICE FACILITY	2525 ORANGE OLIVE ROAD, ORANGE	UNDERGROUND STORAGE TANK LEAK: DIESEL CONTAMINATED SOIL	SITE WORKPLAN SUBMITTED
6/22/04	6/21/04	SHELL SERVICE STATION	1202 EAST YORBA LINDA BOULEVARD, PLACENTIA	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	LEAK BEING CONFIRMED
6/22/04	6/21/04	ALBERTSON'S DISTRIBUTION CENTER	200 NORTH PUENTE STREET, BREA	UNDERGROUND STORAGE TANK LEAK: DIESEL CONTAMINATED SOIL	LEAK BEING CONFIRMED
7/14/04	5/17/04	CIRCLE K #1775	24051 JOHN F. KENNEDY DRIVE, MORENO VALLEY	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	LEAK BEING CONFIRMED
7/23/04	6/12/03	PICK YOUR PART AUTO WRECKING	1235 BEACH BLVD. S., ANAHEIM	UNDERGROUND STORAGE TANK LEAK: CONTAMINATED SOIL	SITE WORKPLAN SUBMITTED

Report date is the date on the Unauthorized Release Report which is filled out by the local agency or the discharger. This report may not contain an accurate listing of all the new cases due to the ongoing reconciliation between the Geotracker/GEIMS, DOD, and Local Agency databases.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
3/3/04	3/3/04	38623	Private Property Owner	1460 W. Lambert, La Habra, Orange County	SSO	1,500	An estimated 1,500 gallons of sewage overflowed from a private manhole due to grease blockage. 500 gallons of the spill were contained, recovered, and returned to the operational sewer system. 1,000 gallons of the spill were discharged to the local storm drain to Cayote Creek and flowed to San Gabriel River. The grease blockage was removed, the affected area was cleaned up and disinfected by a private contractor with assistance of the City of La Habra staff.
4/12/04	4/12/04	38966	Unknown	1500 S. Euclid Avenue, Anaheim, Orange County	SSO	3,456	An estimated 3,456 gallons of sewage overflowed from a manhole due to a "bell" found in the sewer line. 600 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a local storm drain and flowed to Sunset Aquatic Park. Orange County Health Care Agency closed Sunset Aquatic Park for more than 72 hrs. The bell was removed, the affected area was cleaned up and disinfected by the City of Anaheim staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
4/12/04	4/12/04	38983	Private Property Owner	910 S. Euclid St., Anaheim, Orange County	SSO	500	An estimated 500 gallons of sewage overflowed from a private lateral due to grease blockage. 400 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest discharged into a local storm drain. The blockage was removed, the affected area was cleaned up and disinfected by a private contractor with assistance of the City of Anaheim staff.
4/14/04	4/14/04	39143	City of Placentia	234 Wilson Ave., Placentia, Orange County	SSO	500	An estimated 500 gallons of sewage overflowed from a manhole due to grease blockage. All 500 gallons of the spill were discharge into a local storm drain. The blockage was removed, the affected area was cleaned up and disinfected by the City of Placentia staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
4/22/04	4/15/04	38967	Eastern Municipal Water District (EMWD)	13051 Ellsworth St, Moreno Valley, Riverside County	SSO	6,000	An estimated 6,000 gallons of sewage overflowed from a manhole due to a construction debris blockage. 5,600 gallons of the spill were contained, recovered, and returned to the operational sewer system. 400 gallons of the spill were not recovered and percolated into the ground. The debris was removed, the affected area was cleaned up and disinfected by the EMWD staff.
4/18/04	4/18/04	39063	City of Rialto	Holms St. & Sycamore Ave., Rialto, San Bernardino County	SSO	3,960	An estimated 3,960 gallons of sewage overflowed from a manhole due to a construction debris blockage. 3,300 gallons of the spill were contained, recovered, and returned to the operational sewer system. 360 gallons of the spill were not recovered and discharged into a local storm drain. The construction debris was removed, the affected area was cleaned up and disinfected by the City of Rialto's staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
4/19/04	4/19/04	38963	City of Big Bear	Lake Drive, Big Bear Lake, San Bernardino County	SSO	1,000	An estimated 1,000 gallons of sewage overflowed from a wet well of a lift station due to equipment failure. A small amount of the spill was contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into Big Bear Lake. Water samples were taken within the Lake to determine the level of contamination. The lift station was repaired, all alarms were set to normal positions, and the lift station is back to normal operation. The affected area was cleaned up and disinfected by Big Bear City staff.
4/20/04	4/20/04	39064	City of Corona	1034 Rimpau Ave, Corona, Riverside County	SSO	18,000	An estimated 18,000 gallons of sewage overflowed from a manhole due to a construction debris blockage. 8,000 gallons of the sewage were contained, recovered, and returned to the operational sewer system. 10,000 gallons of the spill were not recovered and discharged into a local storm drain and flowed to Temescal Creek. The construction debris was removed, the contaminated area was cleaned up and disinfected by the City of Corona staff. This spill is under investigation by Board staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
4/20/04	4/20/04	39065	Private Property Owner	310 S Mohler, Anaheim, Orange County	SSO	1,000	An estimated 1,000 gallons of sewage overflowed from a private lateral due to grease blockage. 40 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest discharged into a local storm drain and flowed to the Santa Ana River. The blockage was removed, the effected area was cleaned up and disinfected by the private contractor with assistance of the City of Anaheim staff.
4/26/04	4/26/04	38923	City of Orange	3044 North Fairbearing Street, Orange, Orange County	SSO	750	An estimated 750 gallons of sewage overflowed from a manhole due to tree roots blockage. 700 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a local storm drain. The blockage was removed, the affected area was cleaned up and disinfected by the City of Orange staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
4/27/04	4/23/04	39083	Private Liquid Waste Hauler	Between Congress And National Drive, Riverside, Riverside County	SSO	677	An estimated 677 gallons of sewage overflowed from a private liquid waste hauler (Speedy Pumping) due to a broken sight glass level. 339 gallons of the spill contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a local storm drain. The affected area was cleaned up and disinfected by the private contractor.
5/1/04	5/1/04	39003	Construction Contractor	Carnelian south of Vivero, Rancho Cucamonga, San Bernardino County	SSO	1,200	An estimated 1,200 gallons of sewage overflowed from a manhole due to a construction debris blockage. All 1,200 gallons of the spill were contained at the construction area, recovered, and returned to the operational sewer system. The construction debris was removed, the affected area was cleaned up and disinfected by a private contractor with assistance of CVWD's staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
5/1/04	5/1/04	39023	Private Property Owner	18700 Mac Arthur Blv., Irvine, Orange County	SSO	900	An estimated 900 gallons of sewage overflowed from a private lateral due to grease blockage. 700 gallons of the sewage were contained, recovered, and returned to the operational sewer system and while the rest of the spill discharged into a local storm drain. The blockage was removed, the affected area was cleaned up and disinfected by private contractor with assistance of IRWD's staff.
5/7/04	5/6/04	38965	City of Ontario	1000 W Brook, Ontario, San Bernardino County	SSO	1,500	An estimated 1,500 gallons of sewage overflowed from a manhole due to grease blockage. All 1,500 gallons of the spill were contained, recovered, and returned to the operational sewer system. The blockage was released, the affected area was cleaned up and disinfected by the City of Ontario staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
5/7/04	5/7/04	39103	Private Property Owner	Chicago Ave. & 215 Freeway, Riverside, Riverside County	SSO	2,000	An estimated 2,000 gallons of sewage overflowed from an upstream manhole due to construction debris blocking the sewer line. All 2,000 gallons of the spill were discharged into the storm drain. The construction debris was removed, the affected area was cleaned up and disinfected by a private company with assistance of the City of Riverside staff.
5/8/04	5/8/04	38943	Yorba Linda Water District (YLWD)	4931 Ave de los Reyes, Yorba Linda, Orange County	SSO	1,953	An estimated 1,953 gallons of sewage overflowed from a manhole due to a blockage caused by tree roots and grease. Only 25 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a local storm drain and flowed to the Santa Ana River. The tree roots blockage was removed, the affected area was cleaned up and disinfected by YLWD staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
4/23/04	4/22/04	38984	City of Redlands	Redlands STP, Redlands, San Bernardino County	SSO	50,000	An estimated 50,000 gallons of secondary treated and chlorinated sewage overflowed from a wet well inside the plant due to equipment failure. 80% of the spill was contained, recovered, and returned to the headworks of the plant while 20% of the spill discharged into a storm drain and flowed to the dry riverbed of the Santa Ana River. To prevent a repeat of this type of discharge, City of Redlands installed a backup bubbler system which replaces the in plant air compressor system until the entire level indicating system is replaced with a doppler type wet well level indicator.
4/27/04	4/23/04	39083	Private Liquid Waste Hauler	Between Congress And National Drive, Riverside, Riverside County	SSO	677	An estimated 677 gallons of sewage overflowed from a private liquid waste hauler (Speedy Pumping) due to a broken sight glass level. 339 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a local storm drain. The affected area was cleaned up and disinfected by a private contractor.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
4/29/04	4/29/04	39163	City of Redlands	Southeast Side of the Alabama Landfill, Redlands, San Bernardino County	SSO	1,000	An estimated 1,000 gallons of treated secondary effluent discharged from an air relief valve failure. All 1,000 gallons of the spill percolated into ground at the base of Alabama landfill before it could reach any waters of the State. The relief valve was repaired; the affected area was cleaned up and disinfected by the City of Redlands staff.
4/30/04	4/30/04	39145	City of Riverside	Riverside Water Quality Control Plant, Riverside, Riverside County	SSO	22,000	An estimated 22,000 gallons of digested sludge leaked from a digester due to a pipe coupling failure. All 22,000 gallons of the digested sludge were contained in an underground pump station in the plant. All 22,000 gallons of the spill were contained, recovered, and returned to the headworks of the plant. None of the sludge left the plant. The underground pump station was cleaned up and the pipe coupling was repaired by the City of Riverside staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
5/7/04	5/7/04	38964	Unknown	Chicago at I-215, Riverside, Riverside County	SSO	2,000	An estimated 2,000 gallons of sewage leaked from a sewer line due to line break by a contractor. All 1,000 gallons of the spill were contained, recovered, and returned to the operational sewer system. The sewer line was repaired; the affected area was cleaned up and disinfected by the City of Riverside staff.
5/16/04	5/16/04	39303	EVMWD	Corydon & Mission Trail St., Lake Elsinore, Riverside County	SSO	6,900	An estimated 6,900 gallons of sewage overflowed from a few manholes due to debris lodged in the pump impellers of the B-2 lift station. The debris was dumped into the wet well of the lift station by vandals. 2,350 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a surrounding open field where it percolated. The debris was removed; the affected area was cleaned up and disinfected by EVMWD's staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
5/26/04	5/26/04	39323	EMWD	Holland & Hanover, Menifee, Riverside County	SSO	1,140	An estimated 1,140 gallons of sewage overflowed from a manhole due to a grease blockage. All 1,140 gallons of the spill were contained, recovered, and returned to the operational sewer system. The blockage was removed; the affected area was cleaned up and disinfected by EMWD's staff.
6/9/04	6/9/04	39643	City of Fontana	11223 Alder Ave., Bloomington, San Bernardino County	SSO	1,500	An estimated 1,500 gallons of sewage overflowed from a wet well due to a lift station failure. All 1,500 gallons of the spill were discharged into the local storm drain. The lift station was repaired; the affected area was cleaned up and disinfected by the City of Fontana staff.
6/10/04	6/10/04	39527	Private Property Owner	2349 W. La Palma Avenue, Anaheim, County of Orange	SSO	500	An estimate 500 gallons of sewage overflowed from a private manhole due to lateral damage by a contractor. All 500 gallons of the spill were contained, recovered, and returned to the operational sewer system. The damaged lateral was repaired; the affected area was cleaned up and disinfected by a private contractor.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
6/15/04	6/12/04	39526	City of Riverside	Intersection of Rumsey Dr. & Laramie Road, Riverside, Riverside County	SSO	500	An estimated 500 gallons of sewage overflowed from a manhole due to a grease blockage. 50 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a local storm drain. The blockage was removed; the affected area was cleaned up and disinfected by the City of Riverside staff.
6/16/04	6/16/04	39343	OCSD	Corner of Lampson & Industry, Garden Grove, Orange County	SSO	3,000	An estimated 3,000 gallons of sewage overflowed from a manhole due to unknown blockage. 300 gallons of the spill were contained, recovered, and returned to the operational sewer system. 2,700 gallons of the spill discharged into a local storm drain that leads to the Anaheim Barber City Channel. As a result, the OCHCA closed the beach from Sunset Aquatic Marina to Portofino Cove in Huntington Harbor.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
6/21/04	6/21/04	39403	Private Property Owner	1221 Katella Ave., Anaheim, Orange County	SSO	432	An estimated 432 gallons of sewage overflowed from a private property's lateral due to grease blockage. 250 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a local storm drain. The blockage was removed, the affected area was cleaned up and disinfected by a private contractor with assistance of the City of Anaheim staff.
6/22/04	6/21/04	39524	AAA Managment	5600 E. Santa Ana Canyon Rd., Anaheim, County of Orange	SSO	1,000	An estimated 1,000 gallons of sewage overflowed from a private manhole due to a grease blockage. All 1,000 gallons of the sewage spill were contained, recovered, and returned to the operational sewer system. The grease blockage was removed, the affected area was cleaned up and disinfected by a private contractor.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
6/23/04	6/21/04	39263	Lee Lake Water District	22646 Temescal Canyon Road	SSO	240,948	An estimated 240,948 gallons of sewage leaked from a pipeline that had been installed on 6/1/04 by the facility expansion contractor. The pipeline was installed properly, but was not backfilled, which allowed for pipe movement that resulted in the failure that caused the spill. 60,000 gallons of the spill were contained at the facility and returned to the headworks of the plant while the rest of the spill discharged into Temescal Canyon Creek where it flowed to a pond in the creek. The affected area was cleaned up, disinfected, and posted to warn public by LLWD's staff.
6/24/04	6/24/04	39383	Private Property Owner	500 Superior Ave., Newport Beach, Orange County	SSO	500	An estimated 500 gallons of sewage overflowed from a private property's lateral due to unknown blockage. All 500 gallons of the spill were discharged into a local storm drain and flowed to Newport Bay at Harbor Marina. OCHCA closed the bay water area at Harbor Marina in Newport Beach to swimming and diving due to this spill. The blockage was cleared, the affected area was cleaned up and disinfected by a private contractor with assistance of Newport Beach staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
6/25/04	6/25/04	39465	Private Property Owner	604 W. Provential Drive, Anaheim, Orange County	SSO	950	An estimated 950 gallons of sewage overflowed from a private manhole due to grease blockage. Only 20 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a local storm drain. The blockage was removed, the affected area was cleaned up and disinfected by a private contractor with assistance of the City of Anaheim staff.
6/25/04	6/25/04	39685	Private Property Owner	900 W. La Habra Blv., La Habra, Orange County	SSO	5,000	An estimated 5,000 gallons of sewage overflowed from a manhole due to hot asphalt that was dropped into the manhole during road pavement. All 5,000 gallons of the spill were contained, recovered, and returned to the operational sewer system. The pieces of asphalt were removed from the manhole; the affected area was cleaned up and disinfected by the City of La Habra staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
6/27/04	6/27/04	39405	City of Anaheim	2711 Jackson Ave., Anaheim, Orange County	SSO	19,659	An estimated 19,659 gallons of sewage overflowed from a manhole due to tree roots blockage. 12,500 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a local storm drain. The tree roots were removed; the affected area was cleaned up and disinfected by the City of Anaheim staff.
6/30/04	6/30/04	39624	City of Corona	20730 Temescal King Rd., Corona, Riverside County	SSO	13,000	An estimated 13,000 gallons of sewage leaked from a sewer line damaged by the City as a result of an excavation in the area. All 13,000 gallons of the spill were contained in the excavated area, recovered, and returned to the operational sewer system. The damaged sewer line was repaired; the affected area was cleaned up and disinfected by the City of Corona staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
7/1/04	7/1/04	39703	City of Huntington Beach	Yorktown & Newland, Huntington Beach, Orange County	SSO	1,000	An estimated 1,000 gallons of sewage overflowed from a manhole due to a grease blockage. All 1,000 gallons of the spill were contained, recovered, and returned to the operational sewer system. The blockage was removed; the affected area was cleaned up and disinfected by the City of Huntington Beach staff.
7/4/04	7/4/04	39585	City of Rancho Cucamonga	Kenniston and Sugargun, Rancho Cucamonga, San Bernardino County	SSO	500	An estimated 500 gallons of sewage overflowed from a manhole due to a grease blockage. 400 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a local storm drain. The blockage was cleared; the affected area was cleaned up and disinfected by CVWD's staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
7/5/04	7/4/04	39663	City of Ontario	3300 Summer Island, Ontario, San Bernardino	SSO	600	An estimated 600 gallons of sewage overflowed from a manhole due to a grease blockage. All 600 gallons of the spill were contained in the storm drain, recovered, and returned to the operational sewer system. The blockage was removed; the affected area was cleaned up and disinfected by the City of Ontario staff.
7/6/04	7/4/04	39704	Private Property Owner	3553 Chicago Ave., Riverside, Riverside County	SSO	6,600	An estimated 6,600 gallons of sewage overflowed from a private lateral due to a grease blockage. 93% of the spill was contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a local storm drain. The blockage was cleared; the affected area was cleaned up and disinfected by a private contractor with assistance of the City of Riverside staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
7/6/04	7/6/04	39623	Private Property Owner	1650 S. Campus Ave., Ontario, San Bernardino County	SSO	5,000	An estimated 5,000 gallons of sewage overflowed from a private property's manhole due to grease blockage. 3,000 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a local storm drain. The blockage was removed; the affected area was cleaned up and disinfected by a private contractor with assistance of the City of Ontario staff.
7/12/04	7/12/04	39683	Private Property Owner	1000 Dove St., Newport Beach, Orange County	SSO	600	An estimated 600 gallons of sewage overflowed from a private lateral due to a grease blockage. All 600 gallons of the spill discharged into a local storm drain. The blockage was cleared; the affected area was cleaned up and disinfected by a private contractor with assistance of the City of Newport Beach staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
7/14/04	7/12/04	39464	Private Property Owner	1000 Dove St., Newport Beach, Orange County	SSO	600	An estimated 600 gallons of sewage overflowed from a private property's lateral due to a grease blockage. 500 gallons of the spill were contained, recovered, and returned to the operational sewer system while the rest of the spill discharged into a local storm drain. The blockage was removed; the affected area was cleaned up and disinfected by a private contractor with assistance of the City of Newport Beach staff.
7/13/04	7/13/04	39544	Private Property Owner	Westbound Arlington Ave., Riverside, Riverside County	SSO	1,000	An estimated 1,000 gallons of sewage was released from a private (Tava Lanes, 3439 Arlington Ave.) sewer main. This sewer line is connected to a lift station belonging to Tava Lanes. All of the spill was contained, recovered, and returned to the operational sewer system. The broken force main was repaired; the affected area was cleaned up and disinfected by the City of Riverside staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
7/14/04	7/11/04	39469	Private Property Owner.	6101 Morningside, Huntington Beach, Orange County	SSO	3,000	The City of Huntington Beach staff initially estimated 127,008 gallons of sewage overflowed from a private manhole due to heavy grease blockage. The duration of the spill was reported to have been 5-1/2 days and none of the spill was contained or recovered. Upon further investigation, staff found that the spill had occurred for 3-5 hours, and was therefore, only between 2,000 and 3,000 gallons. All the sewage from this spill discharged into a local storm drain and flowed to Bolsa Chica Wetlands. The blockage was removed and the flow restored back to a normal flow by the City of Huntington Beach staff. The property management failed to clean up and remove debris from the affected area, until the next day, after promising the City that they would clean the affected area and repair the damaged pavement and the slope. Board staff is issuing a notice of violation for this spill.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
7/17/04	7/17/04	39684	IEUA	14950 Telephone Ave., Chino Hills, San Bernardino	SSO	63,000	An estimated 63,000 gallons of mixed liquor was released when a clarifier valve was left open during transfer of mixed liquor from one of the clarifiers to another. All 63,000 gallons of the spill were contained in a catch basin, recovered, and returned to the headworks of the IEUA plant. The valve was secured, the affected area was cleaned up and disinfected by IEUA's staff.

Row(s) 1 - 55